

Appliances properties: Rizzoli GmbH - MZ80

May 11, 2017 Rizzoli GmbH MZ80 3 DIN EN 12815 2015 ACTECO SRL 33 1880-CPR-041-15
MZ80 3 DIN EN 12815 2015 ACTECO SRL
DIN EN 12815 2015 ACTECO SRL
DIN EN 12815 2015 ACTECO SRL
DIN EN 12815 2015 ACTECO SRL 33
2015 ACTECO SRL 33
ACTECO SRL 33
33
1880-CPR-041-15
Wood
10
191.4
9.6
_
_

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

^{*} A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Norm : Cookers D - 1.BImSchV A - Austrian regulation referred to Art. 15a B-VG CH - Swiss clean air act

ſ				
Evaluation of	of omiccion	data a	nd officionav I	ignita briguettes

Evaluation of emission data and efficiency Wood

F - Crédit d'impôt à la transition énergétique

Norm : Cookers	Evaluation
D - 1.BlmSchV	!

Evaluation of emission data and efficiency Pellets

Norm : Cookers	Evaluation
D - 1.BlmSchV	ļ.



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information

No information/unknown