

Appliances properties: Rüegg Cheminée Schweiz AG - Violino 65x87

Master data

Date of entry Dec 9, 2016

Manufacturer Rüegg Cheminée Schweiz AG

Model Violino 65x87

Nominal heat output [kW] 13.4

Declared nominal space heating output [kW] Continuous burning appliance

DIN EN 13229 Type test standard

2016 Year of testing

Test laboratory RRF Rhein-Ruhr-Feuerstättenprüfstelle GmbH

13

Number of test laboratory

Number of test report RRF - 29 16 4219



Flue gas values


	Wood
Flue gas mass flow [g/s]	12.1
Flue gas mass flow [g/s]	245
Necessary flue draught [Pa]	12

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)



Connectivity to the central heating system



¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

^{*} A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Evaluation of emission data and efficiency Wood

Norm : Inset appliances (with closed firedoor)	Evaluation
D - 1.BlmSchV	Stufe 2
A - Austrian regulation referred to Art 15a B-VG	2015
CH - Swiss clean air act	✓
DK - Danish regulation for air pollution from wood burners	✓
F - Crédit d'impôt à la transition énergétique	√ 7 ☆

Evaluation of emission data and efficiency Lignite briquettes

Norm : Inset appliances (with closed firedoor)	Evaluation
D - 1.BImSchV	
DK - Danish regulation for air pollution from wood burners	I



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information

No information/unknown